

HLA-B*44 Release Note Page 1 of 2

101.563-24/03 – including *Taq* polymerase 101.563-24u/03u – without *Taq* polymerase

Lot No.: **5K4**

Olerup SSP® HLA-B*44

Product number: 101.563-24/03 – including *Taq* pol.

101.563-24u/03u – without *Tag* pol.

Lot number: 5K4

Expiry date: 2023-11-01

Number of tests: 24 tests – Product No. 101.563-24/24u

3 tests - Product No. 101.563-03/03u

Number of wells per test: 63+1

CHANGES COMPARED TO THE PREVIOUS HLA-B*44 LOT (3H9):

Well	5'-primer	3'-primer	rationale
60	-	Modified	3'-primer modified for improved HLA-specific
			amplification.

THE NUMBER OF WELLS is unchanged.

ALLELE COVERAGE:

B*44:02 to B*44:476, i.e. all the currently recognized HLA-B*44 alleles, will be amplified by the primers in the HLA-B*44 SSP kit; www.ebi.ac.uk/imgt/hla, 2019-July-10, release 3.37.0.

The HLA-B*44 kit enables separation of the confirmed HLA-B*44 alleles as listed in the IMGT/HLA database 3.29.0. An HLA allele is listed as confirmed by IMGT/HLA if it has been sequenced by more than a single laboratory or from multiple sources.

The HLA-B*44 kit also enables identification of many null and alternatively expressed alleles.

The following HLA-B*44 alleles can be distinguished by the different sizes of the HLA-specific PCR product:

Alleles	Primer mix	Alleles	Primer mix
B*44:21, 44:326	21	B*44:78, 44:136	48
B*44:58N, 44:139	47	B*44:79:01-44:79:02, 44:192	44
B*44:69:01, 44:85	26	B*44:94, 44:98	52
B*44:72, 44:93	47	B*44:118, 44:98	31
B*44:74, 44:169	18	B*44:160Q, 44:198N	56

¹Alleles that have been deleted from or renamed in the official WHO HLA Nomenclature up to and including the last IMGT/HLA database release can be retrieved from web page http://hla.alleles.org/alleles/deleted.html.



•LERUP SSP*

HLA-B*44 Release Note Page 2 of 2

101.563-24/03 – including *Taq* polymerase 101.563-24u/03u – without *Taq* polymerase

Lot No.: **5K4**

RESOLUTION IN HLA-B*44 HOMO- AND HETEROZYGOTES:

Good.

INFLUENCE ON THE INTERPRETATION OF HLA-B*44 SUBTYPINGS BY NON-HLA-B*44 ALLELES:

None frequently occurring.

MODIFICATIONS MADE DUE TO COMMENTS FROM CUSTOMERS:

No comments received.

